



# APAS2009 High Speed Camera Control

The following are the instructions for control the Casio high speed camera.

To install the APAS2009 you must first to uninstall the old APAS from your computer as follows:



Then, Download the new APAS-2009 from [www.arielnet.com](http://www.arielnet.com) to specific temporary folder:

- Home
- APAS
- ACES
- Download
- Prices
- Services
- About

## Downloads

Download the [APAS-Wizard-2009](#); Renderer; Gait; Wizard; and APAS-Mobile Integrated in one simple download

[APAS-Wizard-2009 Download \(Click Here\)](#)

[Instructions for Downloading the APAS-2009](#)

[APAS-Mobile-2009 \(Running on USB-2 on any computer\)](#)

[Instructions for download JAVA for Vista Computers and XP - New JAVA-PDF file](#)  
[Instructions for Download JAVA for Vista Computers and XP - New Java - .DOC file](#)

### MEDIA

We helped athletes become world champions. We can help you improve your game tool

[Play video](#)

[Virleins Articles](#)

JAVA files require for Renderer and Gait:

- [jre-1\\_5\\_0\\_01-windows-i586-p.exe - RunTime](#)
- [java3d-1\\_3\\_1-windows-i586-opengl-rt.exe - OpenGL](#)

Or

- [java3d-1\\_3\\_1-windows-i586-directx-rt.exe - DirectX](#)

You need for the new Wizard the following download from Microsoft:

- Home
- APAS
- ACES
- Download
- Prices
- Services
- About

## Downloads

Download the [APAS-Wizard-2009](#);

[Instructions for download JAVA for Vista Computers and XP - New JAVA-PDF file](#)  
[Instructions for Download JAVA for Vista Computers and XP - New Java - .DOC file](#)

### MEDIA


We helped athletes become world champions. We can help you improve your game tool

JAVA files require for Renderer and Gait:

- [jre-1\\_5\\_0\\_01-windows-i586-p.exe - RunTime](#)
- [java3d-1\\_3\\_1-windows-i586-opengl-rt.exe - OpenGL](#)

Or

- [java3d-1\\_3\\_1-windows-i586-directx-rt.exe - DirectX](#)



- Home
- APAS
- ACES
- Download
- Prices
- Services
- About

## Downloads

Download the [APAS-Wizard-2009](#);

[Instructions for download JAVA for Vista Computers and XP - New JAVA-PDF file](#)  
[Instructions for Download JAVA for Vista Computers and XP - New Java - .DOC file](#)


### MEDIA

JAVA files require for Renderer and Gait:

- [jre-1\\_5\\_0\\_01-windows-i586-p.exe - RunTime](#)
- [java3d-1\\_3\\_1-windows-i586-opengl-rt.exe - OpenGL](#)

Or

- [java3d-1\\_3\\_1-windows-i586-directx-rt.exe - DirectX](#)





After downloading the file APAS2009.exe you need to execute it by double clicking on the file. The file will be extracted to C:\Program Files\Ariel Dynamics\APAS. Be aware that the apas2009.exe must go to this location in order for the APAS to operate on the computer.

After extracting the apas2009.exe file you will be able to find the following icon on your desktop:



At that point you have the APAS installed as a “trial test”. In order to make it fully functional you must have a site key from Ariel Dynamics Inc. You need to generate a site code by clicking on the APAS Menu and then on “Update License”:






Copy this code number and send us in email to [apasces@gmail.com](mailto:apasces@gmail.com)

We will send you back a site key to "Paste" it above to the space to initialize the full APAS system.

Now that you can run the APAS system, be aware that you need to set the frame rate for the Casio camera at:



You can run, for example 3 regular cameras at 60hz and mix it with the high speed Casio at 400, for example. Each camera need to set to the correct speed. The transformation module will interpolate the correct timing.

Have a great APAS

Gideon